



Follow-up Service Inspection Report E1219761220201114050

INSPECTION DETAILS			
Date:	2022-02-01	File Number.:	E121976
Responsible Office:	Northbrook	Volume:	1
Inspection Center:	335	CCN:	PTKQ
Product Type:	Motors and Generators, Rebuilt for Use In Hazardous Locations	UL Rep Name:	Stig Randmael
Deliverable Type:	Listed	UL Rep ID:	04393
Party Site Number:	604202	Subscriber Factory No.:	399460-001
Manufacturer Name:	Karsten Moholt A/S	Factory Rep Name	Ms. Eva Kristin Tvedt, 1
Manufacturer Address:	Varemottak Storebotn 70 Kleppesto	Factory Rep Phone:	+47-99631743
		Factory Rep Email:	eva.kristin.tvedt@karsten-moholt.no
Nature of visit:	Regular Inspection	Sample Status:	Samples not required
UL Marks Used?	No	UL Marks Removed?	No
Variation Notice Issued?	No	Inspection Conducted Remotely?	Yes
Comments After Submission:			

PRODUCT DOCUMENTS/PRODUCTION READY VISIT
<p>No products examined – Production Ready Visit</p> <p>Authorization to use the UL Mark is contingent upon a regular countercheck of the products intended to be UL Labeled to ensure compliance to UL requirements. Since there was no completed UL Labeled production at the time of this inspection, please notify your UL Field Representative (named on this report) as soon as the next production date or dates are known, so that a UL inspection can be conducted during production of UL Marked products.</p>

SAMPLE DOCUMENTS			
If samples are required to be sent to UL, indicate below. If required samples are not sent, explain in the Comments area.			
No Samples			
Additional Comments	Seny myUL registration package		

In addition to the requirements specified in the applicable UL Services agreement and Follow-Up Service Procedure, UL further defines responsibilities, duties and requirements for both manufacturers and UL representatives in the document titled "UL Mark Surveillance Requirements" that can be located at www.ul.com/fus, and in accordance with the applicable terms and conditions of the document at www.ul.com/responsibilities. Manufacturers without Internet access may obtain the current versions of these documents from their local UL customer service representative or UL field representative.



333 Pfingsten Road
Northbrook, Illinois 60062-2096
United States Country Code (1)
(847) 272-8800
FAX No. (847) 272-8129
<http://www.ul.com>

File E121976

Vol 1

Issued 01/19/1989
Revised 01/18/2000

FOLLOW-UP SERVICE PROCEDURE
(TYPE L)

MOTORS AND GENERATORS, REBUILT FOR USE IN
HAZARDOUS LOCATIONS
(PTKQ)

Manufacturer: KARSTEN MOHOLT A/S
(399460-001) MICH KROHNSGT 86
PO BOX 2458
SOLHEIMSVIKEN
5824 BERGEN NORWAY

Applicant: SAME AS MANUFACTURER
(399460-001)

Listee: SAME AS MANUFACTURER
(399460-001)

This Procedure authorizes the above Manufacturer to use the marking specified by Underwriters Laboratories Inc. only on products covered by this Procedure, in accordance with the applicable Follow-Up Service Agreement.

The prescribed Mark or Marking shall be used only at the above manufacturing location on such products which comply with this Procedure and any other applicable requirements.

The Procedure contains information for the use of the above named Manufacturer and representatives of Underwriters Laboratories Inc. and is not to be used for any other purpose. It is lent to the Manufacturer with the understanding that it is not to be copied, either wholly or in part, and that it will be returned to Underwriters Laboratories Inc. upon request.

This PROCEDURE, and any subsequent revisions, is the property of UNDERWRITERS LABORATORIES INC. and is not transferable.

UNDERWRITERS LABORATORIES INC.

Robert H. Levine
Sr. Vice President and
Chief U.S. Operations Officer